



Treatment and Analysis of a Paint Chip From "Water Lilies" a Fire Damaged Monet

Sharon K.R. Miller, Bruce A. Banks
Glenn Research Center, Cleveland, Ohio

Greg Tollis
Cleveland State University, Cleveland, Ohio

The NASA STI Program Office . . . in Profile

Since its founding, NASA has been dedicated to the advancement of aeronautics and space science. The NASA Scientific and Technical Information (STI) Program Office plays a key part in helping NASA maintain this important role.

The NASA STI Program Office is operated by Langley Research Center, the Lead Center for NASA's scientific and technical information. The NASA STI Program Office provides access to the NASA STI Database, the largest collection of aeronautical and space science STI in the world. The Program Office is also NASA's institutional mechanism for disseminating the results of its research and development activities. These results are published by NASA in the NASA STI Report Series, which includes the following report types:

- **TECHNICAL PUBLICATION.** Reports of completed research or a major significant phase of research that present the results of NASA programs and include extensive data or theoretical analysis. Includes compilations of significant scientific and technical data and information deemed to be of continuing reference value. NASA's counterpart of peer-reviewed formal professional papers but has less stringent limitations on manuscript length and extent of graphic presentations.
- **TECHNICAL MEMORANDUM.** Scientific and technical findings that are preliminary or of specialized interest, e.g., quick release reports, working papers, and bibliographies that contain minimal annotation. Does not contain extensive analysis.
- **CONTRACTOR REPORT.** Scientific and technical findings by NASA-sponsored contractors and grantees.
- **CONFERENCE PUBLICATION.** Collected papers from scientific and technical conferences, symposia, seminars, or other meetings sponsored or cosponsored by NASA.
- **SPECIAL PUBLICATION.** Scientific, technical, or historical information from NASA programs, projects, and missions, often concerned with subjects having substantial public interest.
- **TECHNICAL TRANSLATION.** English-language translations of foreign scientific and technical material pertinent to NASA's mission.

Specialized services that complement the STI Program Office's diverse offerings include creating custom thesauri, building customized data bases, organizing and publishing research results . . . even providing videos.

For more information about the NASA STI Program Office, see the following:

- Access the NASA STI Program Home Page at <http://www.sti.nasa.gov>
- E-mail your question via the Internet to help@sti.nasa.gov
- Fax your question to the NASA Access Help Desk at 301-621-0134
- Telephone the NASA Access Help Desk at 301-621-0390
- Write to:
NASA Access Help Desk
NASA Center for AeroSpace Information
7121 Standard Drive
Hanover, MD 21076



Treatment and Analysis of a Paint Chip From "Water Lilies" a Fire Damaged Monet

Sharon K.R. Miller, Bruce A. Banks
Glenn Research Center, Cleveland, Ohio

Greg Tollis
Cleveland State University, Cleveland, Ohio

Prepared for the
2001 Fall Meeting
sponsored by the Materials Research Society
Boston, Massachusetts, November 26–30, 2001

National Aeronautics and
Space Administration

Glenn Research Center

Acknowledgments

The authors would like to thank Winstone Wells, Dianne Modestini, and Molly March of the New York University Conservation Center for the Institute of Fine Arts for the opportunity to conduct tests on the paint chip from the fire damaged Monet "Water Lilies" painting and for many helpful discussions.

Trade names or manufacturers' names are used in this report for identification only. This usage does not constitute an official endorsement, either expressed or implied, by the National Aeronautics and Space Administration.

Available from

NASA Center for Aerospace Information
7121 Standard Drive
Hanover, MD 21076

National Technical Information Service
5285 Port Royal Road
Springfield, VA 22100

Available electronically at <http://gltrs.grc.nasa.gov/GLTRS>

TREATMENT AND ANALYSIS OF A PAINT CHIP FROM “WATER LILIES” A FIRE DAMAGED MONET

Sharon K.R. Miller and Bruce A. Banks
National Aeronautics and Space Administration
Glenn Research Center
Cleveland, Ohio 44135

Greg Tollis
Cleveland State University
Cleveland, Ohio 44115

ABSTRACT

A museum fire in 1958 severely damaged a Monet “Water Lilies” (1916–1926) painting that was on display. The surface of the painting is very dark with areas of blistering and charring. Over the years, traditional techniques have been found to be ineffective at removal of the soot and char from the surface. The painting, which is now in the care of the New York University (NYU) Conservation Center of the Institute of Fine Arts, was the subject of a study to determine if atomic oxygen treatment could remove the soot and char without damaging the fragile painting underneath. For test purposes, a small chip of paint was removed from the edge of the painting by a conservator at NYU and supplied to NASA Glenn Research Center for atomic oxygen treatment and analysis. The diffuse spectral reflectance, at three locations on the paint chip, was monitored at intervals during the atomic oxygen treatment process. Photo documentation of the chip during treatment was also performed. The color contrast was calculated from the spectral reflectance data as a function of treatment duration. Results of the testing indicated that the contrast improved as a result of the treatment, and the differentiation of colors on the surface was significantly improved. Soot and char could be removed without visibly affecting the gross surface features such as impasto areas. These results indicate the feasibility for the treatment of the “Water Lilies” painting.

INTRODUCTION

Research on atomic oxygen as a treatment technique for art applications started through inquiries by the Conservation Department of the Cleveland Museum of Art and discussions with many conservators representing museums and private studios worldwide. The primary interest has been as a tool for removing fire damage from the surface of fine art.

Atomic oxygen is present in Earth’s atmosphere at altitudes where satellites typically orbit. It has been shown to react chemically with surfaces or deposits that contain carbon [1,2]. The reaction converts the carbon to volatile species such as carbon monoxide. Materials already in a high oxidation state such as the metal oxides used in many paint pigments are typically not affected by atomic oxygen. Ground based facilities for producing atomic oxygen have been developed for testing the materials that are used to construct low Earth orbiting satellites [3,4]. These facilities dissociate molecular oxygen into atomic oxygen by radio frequency, microwave radiation, or electron bombardment typically under a partial vacuum between 0.027 and 20 Pa (2×10^{-4} to 0.15 torr) depending on the oxygen dissociation process used.

Atomic oxygen is of interest for cleaning fine art because the process is in the gas phase, therefore there is no mechanical contact, and the reaction is confined to the surface, which

reduces the risk of damaging the underlying paint or canvas. The atomic oxygen cleaning technique has been used to effectively remove soot from canvas, acrylic gesso, a watercolor, and several oil paintings [5,6,7].

Conservators at New York University (NYU) Conservation Center of the Institute of Fine Arts were interested in determining if atomic oxygen could remove soot and char from a fragile "Water Lilies" painting that was damaged in a museum fire in 1958. Edges of the painting have been the object of many conservation treatment investigations over the years. However, no acceptable restoration process has been identified to date. This study investigates the viability of atomic oxygen treatment for removing soot and char from a paint chip removed from the edge of the "Water Lilies" painting.

APPARATUS AND PROCEDURE

The irregularly shaped paint chip, roughly 1.25 cm by 1 cm, was mounted onto a sheet of aluminum $5.08 \times 7.62 \times 0.1524$ cm using Elmer's white glue. The chip was mounted so that the aluminum could be used as a support to keep the chip intact during transfer from treatment to analysis, and also to act as a reference guide for lining up the sample for viewing in the microscope and making diffuse reflectance measurements. The mount and adhesive also protected the backside of the chip from exposure to atomic oxygen.

Examination and photo-documentation of the paint chip prior to, during and after atomic oxygen treatment was performed using an Olympus SZH Stereo Zoom Microscope and camera. Initially the chip was viewed and photographed with the microscope, and then three areas were selected for monitoring through the treatment process based on uniformity of the damage over a 0.3175 cm diameter area (approximate illumination and detection area of the spectrophotometer), and flatness. The coordinates of each area (A, B, and C), as shown in Figure 1, were recorded using a Boeckeler X-Y translation system on the microscope stage so that the same area could be returned to for examination during the treatment process.




Figure 1. Monet "Water Lilies" paint chip showing sampling locations

Atomic oxygen treatment was performed in a small vacuum plasma chamber (SPI Plasma Prep II) operated on air at pressures of 12.7 to 16 Pa (95 to 120 mTorr). The air was dissociated into atomic oxygen using radio frequency radiation. The mounted paint chip was placed inside the vacuum chamber on top of glass slides for treatment.

Diffuse reflectance measurements, at each of the selected coordinates, was made prior to, at intervals during, and after atomic oxygen treatment using an Ocean Optics Spectrophotometer. In order to keep the spectrophotometer aligned with each of the coordinates, the translation system was removed from the microscope stage and mounted onto a stage that supported the spectrophotometer light source and detector in a fixed position. These measurements were made in order to quantify changes in the surface of the chip with regard to the shape of the spectral curve (color), as well as the color contrast as a function of treatment time. The diffuse reflectance from the surface was measured over the wavelength range of 450 to 650 nm because it covers the majority of the spectrum over which the human eye is sensitive [8]. Contrast was determined by observation of the wavelengths that gave the highest and lowest reflectance levels with exposure and then comparing the difference between the reflectance values at these wavelengths as a function of treatment. The result is an indication of the color contrast within the measured area due to treatment. The end point of the treatment process is indicated by contrast values that change little and the shape of the diffuse reflectance as a function of wavelength curve remaining fairly stable with increasing treatment time.

DISCUSSION

The diffuse reflectance as a function of wavelength at location A on the paint chip is shown in Figure 2. The plot is similar to that obtained in area C. The plot shows an initial reflectance that was low and very flat which is indicative of a uniformly dark gray surface. As the chip was treated with atomic oxygen, the reflectance began to increase overall and exhibit a greater increase in reflectance in the region of approximately 450 to 510 nm, which is the blue region of the spectrum. Area B lightened a little but did not show as marked a change in the shape of the curve, which may be due to the central area of the measurement not being as soot covered as areas A and C initially. This can be seen in Figure 3, a plot of the contrast for each of the three areas as a function of treatment dose or fluence, which is represented by the number of atoms that arrived at a square centimeter of the paint chip over the duration of the exposure. With treatment, sample location A and C contrast values generally increased to a limiting value, while that for location B remained fairly constant.

After treatment was concluded, a Grumbacher Acrylic Picture Varnish was sprayed on the chip in a light mist. The varnish serves to prevent the pigment, which is now loosely bound to the surface after treatment, from being inadvertently removed. It also acts as a fill for the charred binder that was removed and causes the paint colors to become more saturated. This is represented by a greater differentiation between diffuse reflectance measurements obtained over specific segments of the wavelength region and can result in either a decrease or increase in contrast depending on the angle at which the reflectance is measured. Pigment particles that are loosely bound tend to reflect in more directions with respect to the surface by scattering the incoming light, while addition of a binder between the particles reduces the scatter and makes the reflection from the surface more specular.




Figure 2. Diffuse Spectral Reflectance for selected intervals of atomic oxygen treatment at sample location A on the Monet "Water Lilies" paint chip




Figure 3. Contrast at selected locations on the Monet "Water Lilies" paint chip as a function of atomic oxygen treatment

Figure 4 contains microscope photographs of the paint chip showing the region surrounding and including location A, prior to treatment, after atomic oxygen treatment, and after treatment and application of varnish. The atomic oxygen treatment was able to effectively remove the soot from the surface of the chip and expose bright blue and green pigments, whose colors were further saturated by addition of the acrylic varnish. As can be observed from the photographs, surface features and overall texture of the paint remained undisturbed through the treatment process.

These results indicate the feasibility for the treatment of the Monet “Water Lilies” painting. It appears that atomic oxygen treatment can remove the soot and char and expose the pigments without greatly altering the surface features that are present. If the paint on the surface flowed due to the heat of the fire, this would not be affected by atomic oxygen treatment so it is unclear whether or not a full recovery of the painting is possible. The treatment of the chip was performed in a small radio frequency plasma chamber, however, larger paintings have been treated in the past in a larger radio frequency plasma chamber that could accommodate the Monet painting. Careful observation and recording of the process by both conservators and scientists would be needed to enable the full painting to be treated safely.




Figure 4. Region surrounding and including location A: a. prior to treatment, b. after atomic oxygen treatment, c. after atomic oxygen treatment and application of acrylic varnish

CONCLUSIONS

Results of atomic oxygen treatment of a chip from the edge of a fire damaged Monet “Water Lilies” painting indicate that atomic oxygen was able to effectively remove soot from the surface and expose the underlying paint pigments. Increases in diffuse reflectance and contrast were observed on selected areas of the paint chip during treatment. Microscope observation also indicated that surface features and overall texture were preserved through the treatment process. With careful documentation and treatment by conservators and scientists, it appears feasible that the soot and char can be effectively removed from the Monet “Water Lilies” painting.

REFERENCES

1. B. Banks, S. Rutledge, J. Brady, and J. Merrow, "Atomic Oxygen Effects on Materials," *NASA/SDIO Space Environmental Effects on Materials Workshop*, (NASA Conference Publication 3035, Hampton, VA, 1988) pp. 197–239.
2. B.A. Banks, S.K. Rutledge, "Low Earth Orbital Atomic Oxygen Simulation for Materials Durability Evaluation," *Proceedings of the Fourth European Symposium on Spacecraft Materials in the Space Environment*, (CERT, Toulouse, France, 1988), pp. 371–92.
3. B.A. Banks, S.K. Rutledge, P.E. Paulsen, and T.J. Stueber, "Simulation of Low Earth Orbital Atomic Oxygen Interaction with Materials by Means of an Oxygen Ion Beam," *18th Annual Symposium on Applied Vacuum Science and Technology*, (1989), NASA TM-101971.
4. C.S. Stidham, T.J. Stueber, B.A. Banks, J.A. Dever, and S.K. Rutledge, "Low Earth Orbital Atomic Oxygen Environmental Simulation Facility for Space Materials Evaluation," *38th International SAMPE Symposium and Exhibition*, (Anaheim, CA, 1993), NASA TM-106128.
5. S. Rutledge, B. Banks, M. Forkapa, T. Stueber, E. Seckar, and K. Malinowski, "Atomic Oxygen Treatment as a Method of Recovering Smoke-Damaged Paintings," *Journal of the American Institute for Conservation of Historic and Artistic Works* **39**, (2000), pp. 65–74.
6. S.K. Rutledge, B.A. Banks, and V.A. Chichernea, "Recovery of a Charred Painting Using Atomic Oxygen Treatment," *Proceedings of the 12th Triennial Meeting of the International Committee for Conservation, ICOM*, (Lyon, France, 1999), pp. 330–335.
7. S.K. Rutledge, B.A. Banks, V.A. Chichernea, and C.A. Haytas, "Cleaning of Fire Damaged Watercolor and Textiles Using Atomic Oxygen," *18th International Congress of the International Institute for Conservation of Historic and Artistic Works, IIC*, (Melbourne, Australia, 2000), NASA/TM—2000-210335.
8. L.R. Koller, *Ultraviolet Radiation* 2nd Edition, John Wiley & Sons, New York (1965) pp. 6–7.

REPORT DOCUMENTATION PAGE			<i>Form Approved OMB No. 0704-0188</i>
<p>Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.</p>			
1. AGENCY USE ONLY (Leave blank)	2. REPORT DATE	3. REPORT TYPE AND DATES COVERED	
	December 2001	Technical Memorandum	
4. TITLE AND SUBTITLE		5. FUNDING NUMBERS	
Treatment and Analysis of a Paint Chip From "Water Lilies" a Fire Damaged Monet		WU-755-A4-13-00	
6. AUTHOR(S)		7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)	
Sharon K.R. Miller, Bruce A. Banks, and Greg Tollis		National Aeronautics and Space Administration John H. Glenn Research Center at Lewis Field Cleveland, Ohio 44135-3191	
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)		8. PERFORMING ORGANIZATION REPORT NUMBER	
National Aeronautics and Space Administration Washington, DC 20546-0001		E-13135	
11. SUPPLEMENTARY NOTES		10. SPONSORING/MONITORING AGENCY REPORT NUMBER	
<p>Prepared for the 2001 Fall Meeting sponsored by the Materials Research Society, Boston, Massachusetts, November 26-30, 2001. Sharon K.R. Miller and Bruce A. Banks, NASA Glenn Research Center; and Greg Tollis, Cleveland State University, Cleveland, Ohio 44115. Responsible person, Sharon K.R. Miller, organization code 5480, 216-433-2219.</p>			
12a. DISTRIBUTION/AVAILABILITY STATEMENT		12b. DISTRIBUTION CODE	
Unclassified - Unlimited Subject Category: 27		Distribution: Nonstandard	
<p>Available electronically at http://gltrs.grc.nasa.gov/GLTRS This publication is available from the NASA Center for AeroSpace Information, 301-621-0390.</p>			
13. ABSTRACT (Maximum 200 words)			
<p>A museum fire in 1958 severely damaged a Monet "Water Lilies" (1916-1926) painting that was on display. The surface of the painting is very dark with areas of blistering and charring. Over the years, traditional techniques have been found to be ineffective at removal of the soot and char from the surface. The painting, which is now in the care of the New York University (NYU) Conservation Center of the Institute of Fine Arts, was the subject of a study to determine if atomic oxygen treatment could remove the soot and char without damaging the fragile painting underneath. For test purposes, a small chip of paint was removed from the edge of the painting by a conservator at NYU and supplied to NASA Glenn Research Center for atomic oxygen treatment and analysis. The diffuse spectral reflectance, at three locations on the paint chip, was monitored at intervals during the atomic oxygen treatment process. Photo documentation of the chip during treatment was also performed. The color contrast was calculated from the spectral reflectance data as a function of treatment duration. Results of the testing indicated that the contrast improved as a result of the treatment, and the differentiation of colors on the surface was significantly improved. Soot and char could be removed without visibly affecting the gross surface features such as impasto areas. These results indicate the feasibility for the treatment of the "Water Lilies" painting.</p>			
14. SUBJECT TERMS			15. NUMBER OF PAGES
Monatomic gases; Oxygen; Restoration; Arts; Fire damage			12
			16. PRICE CODE
17. SECURITY CLASSIFICATION OF REPORT	18. SECURITY CLASSIFICATION OF THIS PAGE	19. SECURITY CLASSIFICATION OF ABSTRACT	20. LIMITATION OF ABSTRACT
Unclassified	Unclassified	Unclassified	